

OEnoviaFioul Confort OSCR 45 - OSCR 60 - OSCR 90 – OSCR 120

Diagnostic	aid -	Evolutions

For your Information and diagnostic aid :

1. First of all, check that the installation complies with the **rules to be followed** as indicated in the technical information <u>ITOE0229</u>.

N° **ITOE0232-en**

2. 2. Check the following evolutions and improvements, which may provide a solution if problems persist.

IMPORTANT: A preventive update is not necessary !

Symptoms / Error- Codes (Please also refer to the list of error codes in the manual)	Other possible causes (in addition to the causes listed in the manual)	Evolutions / Description	Appliances concerned / Application dates
 Starting difficulties: ignition or flame detection failure: E07.14 (Burner 1) E07.29 (Burner 2) Flame loss: H01.03 E07.20 (Burner 1) E07.35 (Burner 2) 	The flame tube can become loose and create a parasitic recirculation.	Flame tube with a locking boss. Flame tube with a locking boss. Flame tube set of the	Only OSCR 60 /120 04.03.2020 from burner serial number starting with : 040320
- Starting difficulties: ignition or flame detection failure: E07.14 (Burner 1) E07.29 (Burner 2)	Spray angle too narrow	New Steinen oil nozzle 80°S with larger spraying angle, facilitates ignition.	Only OSCR 60 /120 02.01.2020 from burner serial number starting with : 020120





JS

31/08/2020

EN

Symptoms / Error- Codes (Please also refer to the list of error codes in the manual)	Other possible causes (in addition to the causes listed in the manual)	Evolutions / Description	Appliances concerned / Application dates
 Flame detection difficult Ignition fault: E07.14 (Burner 1) E07.29 (Burner 2) Flame loss: H01.03 E07.20 (Burner 1) E07.35 (Burner 2) 	Under certain conditions, the KLC 2002 flame detection cell does not deliver a reliable signal (two- phase networks, floating neutral, etc.).	New flame detection cell IRD 1010.1. Image: Provide and Annual States Spare parts: 7611747 Flame detection cell IRD 1010.1 (red)	All 17.09.2019 from burner serial number starting with: 170919
- Untimely ignition failures: E07.14 (Burner 1) E07.29 (Burner 2)	The RV safety control box with software 117 can be disturbed by the communication with the control system during the safety time, and report a "flame fault" even if the flame is detected.	The new software version 119 of the RV safety control box solves this problem. To check the software version, see the label:	Mainly OSCR 60 /120 (Modification applied to the whole range). 18.03.2020 from burner serial number starting with: 180320
- Burner motor error : E07.16 (Burner 1) E07.31 (Burner 2)	The 2 components (safety control box and motor control	The RV safety control box with software 120 incorporates a new logic that increases the tolerance ranges to reduce the number of trigger occurrences. To check the software version, see the label: $\underbrace{\begin{tabular}{lllllllllllllllllllllllllllllllllll$	All Foreseen introduction date in the factory: 30.09.2020
	box) contain a motor monitoring function which can trigger a safety shutdown in case of a fluctuation of the mains voltage or micro cut-offs.	 New version of the motor control box: Software-Version (Rev AG) : the minimum switching power of the motor control box has been lowered. Hardware-Evolution (from serial number starting with E4) : resistance changed to increase the high limit. To check the software version, see the label: Drving extronice Rev AG Spare parts: 7661523 Motor control box for modulating burner. 	All 18.03.2020 from burner serial number starting with : 180320

Symptoms / Error- Codes (Please also refer to the list of error codes in the manual)	Other possible causes (in addition to the causes listed in the manual)	Evolutions / Description	Appliances concerned / Application dates
- The display or the boiler switches off for no reason.	False contact or gap at the on/off switch.	Evolution of the PCB protection A with maintaining B of the switch connector.	All 08.04.2019
 Starting difficulties: ignition or flame detection failure: E07.14 (Burner 1) E07.29 (Burner 2) Flame loss: H01.03 E07.20 (Burner 1) E07.35 (Burner 2) 	Fuel oil connection at the inlet of the deaerator filter not in accordance with the regulations (the use of Teflon or conical connections is prohibited). Air inlets on oil supply pipework.	In order to enable the installer to connect the oil filter deaerator to the tank in accordance with the rules of good practice, a connection kit is delivered in the MT11 package (deaerator filter). This kit contains an adapter with an O-ring seal on the filter side and an olive on the oil supply pipe side, for 3 different copper pipe diameters (O.D./I.D. 6/4 mm, 8/6 mm and 10/08 mm). Spare parts: this connection kit is available in the Spare Part Centre: 7753997 Connection kit for Flocotop	All 30.07.2020
 Starting difficulties: ignition or flame detection failure: E07.14 (Burner 1) E07.29 (Burner 2) Flame loss: H01.03 E07.20 (Burner 1) E07.35 (Burner 2) Grazing (pulsations) during combustion. 	Early wear of the combustion chamber door insulation, which can block the 2nd smoke passage in the upper part of the exchanger.	Improvement of the fastening and the material of the insulation of the combustion chamber door. A new insulation (item 5) and a new combustion chamber door assembly (item 3) with improved insulation and closure, are fitted in factory.	Mainly OSCR 60 /120 15.06.2020 (Insulation from: 17.06.2019) This change is introduced gradually on all models.

Symptoms / Error- Codes (Please also refer to the list of error codes in the manual)	Other possible causes (in addition to the causes listed in the manual)	Evolutions / Description	Appliances concerned / Application dates
- Burner short- cycles , non- optimised modulation	The P/I parameters of the CU-OH-02 PCB are not optimized.	Evolution and optimisation of the CU-OH-02 PCB, new soft version 1.03 : optimised heating mode modulation parameters, to make operating cycles longer and reduce the number of starts.	All
 Activities not saved after an ON/OFF, No reporting of burner errors from EA to EF. 	Old version of the CU-OH-02 PCB.	Spare parts: 7677421 CU-OH-02 PCB	09.09.2019
- The boiler remains on standby in spite of the heating demand.	If the heating demand disappears during a flame loss followed by a restart of the burner, the control no longer reacts to a new heating demand. Solution: Switch the power ON/OFF.	Software-Version 1.04 of CU-OH-02 PCB solves this problem.	All 31.08.2020
- The fault history contains many occurrences of faults OTH ASK H02.53, H02.54	Old SCB-10C PCB version.	Scenario D Scenario D <td>All 01.04.2019</td>	All 01.04.2019

Check the burner serial number:

Coding of the burner **serial number** (From June 1st 2017) :



Burner nameplate:

1 = 6 first digits = Manufacturing date:

19_05_17 = 19 May 2017 (Example)

2 = 12 digits : **Counter** (reset to 0 on January 1st of the year).